QUALITY ASSURANCE DEPARTMENT



STANDARD OPERATING PROCEDURE

Department: Quality Assurance	SOP No.:
Title: Procedure for Operation & Cleaning of Lux Meter	Effective Date:
Supersedes: Nil	Review Date:
Issue Date:	Page No.:

1.0 OBJECTIVE:

To lay down a Procedure for Operation and Cleaning of Lux meter.

2.0 SCOPE:

This SOP is applicable for Operation and Cleaning of Lux meter at

3.0 RESPONSIBILITY:

Officer/Executive QA: shall be responsible measure the Lux level at all locations of the plant using Lux Meter.

4.0 ACCOUNTABILITY:

Head QA: To ensure compliance and implementation of this SOP.

5.0 **DEFINITION:**

Not Applicable

6.0 PROCEDURE:

6.1 Operation:

- 6.1.1 Before use ensure that Lux Meter is calibrated and calibration tag is affixed on it.
- **6.1.2** Remove the Protection cap of Lux Meter to see the digital display as shown below:



6.1.3 Basic settings of Lux Meter are:

QUALITY ASSURANCE DEPARTMENT



STANDARD OPERATING PROCEDURE

Department: Quality Assurance	SOP No.:
Title: Procedure for Operation & Cleaning of Lux Meter	Effective Date:
Supersedes: Nil	Review Date:
Issue Date:	Page No.:



The displayed parts from 1 to 5 are the following:

- 1. Protection cap: Park position
- 2. Light sensor
- 3. Display
- 4. Control keys
- 5. Battery compartment (on rear)
 - **6.1.3.1** To switch off the Instrument press and hold (a) until the display goes off.
 - 6.1.3.2 To switch on the instrument press (1) measuring mode is opened.
 - **6.1.3.3** Switching the display light on press (1), the display light goes out automatically if no key is pressed for 10 seconds.
 - **6.1.3.4** For Changing the parameter unit press \blacktriangle until the desired unit (lux or ftc) appears.
 - **6.1.3.5** Select display mode with ^(e) then Readings are Hold, again press ^(e) to see the Maximum reading, finally press ^(e) then Minimum reading appear on display
- 6.1.4 Switch ON the Lux meter by pressing .
- 6.1.5 Ensure no low battery indication on display, if found replace the battery refer point no.6.4
- 6.1.6 Ensure initial reading of Lux Meter shall be "Zero".
- 6.1.7 The operating range of Lux Meter to measure Lux level is 0 to 99999 lux.
- 6.1.8 Hold the light sensor facing towards light source in a horizontal position.

QUALITY ASSURANCE DEPARTMENT



STANDARD OPERATING PROCEDURE

Department: Quality Assurance	SOP No.:
Title: Procedure for Operation & Cleaning of Lux Meter	Effective Date:
Supersedes: Nil	Review Date:
Issue Date:	Page No.:

- **6.1.9** Place the Lux meter sensor on working plane i.e. at the height one meter approximately from the floor level.
- **6.1.10** The display will show Lux value.
- **6.1.11** Hold the Lux meter at minimum five locations (Take 5 readings in an area at different location).
- 6.1.12 The average Lux of all readings will be the Lux level in area.
- **6.1.13** Switch OFF the Lux meter by pressing (1) until the display goes off.
- **6.1.14** Conduct the Lux monitoring activity in all areas at yearly basis.
- **6.1.15** During Lux level monitoring, if any reading found less than required reading then do the required maintenance work in respective area for improvement of Lux level.

6.2 Cleaning:

- 6.2.1 Instrument should be Switch "OFF" before cleaning
- **6.2.2** Clean the all the surface of Instrument with dry lint free cloth. Do not use aggressive cleaning agents or solvents.

6.3 Handling:

- **6.3.1** Handle the instrument carefully.
- **6.3.2** Hard blow to the exterior of the instrument may cause damage.
- **6.3.3** Display which may result in cracking the thin touch screen glass.
- **6.3.4** Never store the instrument together with solvents, acids or other aggressive substances.

6.4 Maintenance:

- 6.4.1 For changing the batteries open the battery compartment, push the battery cover down.
- **6.4.2** Remove used batteries and insert new batteries. Observe the polarity.
- **6.4.3** To close the battery compartment, push the battery cover back on.

6.5 Acceptance criteria:

QUALITY ASSURANCE DEPARTMENT



STANDARD OPERATING PROCEDURE

Department: Quality Assurance	SOP No.:
Title: Procedure for Operation & Cleaning of Lux Meter	Effective Date:
Supersedes: Nil	Review Date:
Issue Date:	Page No.:

6.5.1 Light intensity at the normal working and height should not be less than 300 Lux.

6.6 Calibration:

6.6.1 Lux meter shall be calibrated on yearly basis from outside agency.

7.0 ABBREVIATIONS:

- SOP : Standard Operating Procedure
- QA : Quality Assurance
- Pvt. : Private
- Ltd. : Limited

8.0 ANNEXURES:

NA

9.0 **DISTRIBUTION:**

- Master Copy
 Quality Assurance Department
- Controlled Copy No. 01 Quality Assurance Department

10.0 REFERENCES:

In-House

11.0 REVISION HISTORY:

Revision No.	Change Control No.	Details of Changes	Reason of Changes	Effective Date	Done By
00	Not Applicable	Not Applicable	New SOP		