

ENVIRONMENT HEALTH SAFETY DEPARTMENT

HAZARD IDENTIFICATION AND RISK ASSESSMENT

Denar	pepartment: Compression									Date:					
	Team:	951011					Location:								
S.No.	Activity	Sub- Activity	Hazard	N/A/E	Risk	Existing control Measure	e	Risk nsider xistin contro neasu	g l	Addition control measures to bring risk to (ALARP level)	Residual risk after applying additional control measures		lying nal ol	Remar ks (if Any)	
							Frequency	Severity	RPN (F*S)	 Elimination Substitution Engg. Control Administratio n Control PPE's 	Frequency	Severity	RPN (F*S)		
1.	Compression	Assembly of Compression machine.	 Defective tools Sharp edges. Electrical hazards 	A	 Musculoskelet al disorder. Electrocution. Entanglement. Slip & trip. Struck by an object. 	35	3	2	6	345	3	1	3		

FORMAT No.: Page 1 of 5



ENVIRONMENT HEALTH SAFETY DEPARTMENT

HAZARD IDENTIFICATION AND RISK ASSESSMENT

2.	Compression	Shifting machine from zero level to 1st floor.	 Hydras Crane Defective lifting tools & tackles. Inexperienc e riggers Suspended load. Inexperienc ed signal man. 	Е	 Struck by an object. Slip & trip Failure of lifting tools & tackles. Toppling of hydras & cranes due to uneven ground. 	345	4	3	12	2345	4	2	8	-
3.	Compression	Handling and storage of material.	 Sharp edges Manual handling. Shifting by trolley Poor housekeeping Lack of space 	A	 Back injuries Cut injuries Slip & trip Fall of material Entanglement Struck by an object. 	45	3	2	6	345	3	1	3	-

FORMAT No.: Page 2 of 5



ENVIRONMENT HEALTH SAFETY DEPARTMENT

HAZARD IDENTIFICATION AND RISK ASSESSMENT


4.	Compre ssion	Filling of material from drum to compressi on hopper	Sharp edgesLack of spaceSpillage	A	Back injuriesCut injuriesFall of material	35	3	2	6	345	3	1	3	-
5.	Compre	During operation of machine	 Sharp edges Unprotect moving Parts Electrocution Slip & Trip Dust Particles 	E	 Cut injuries. Electric shock. Dust generation Inhalation of dust. Eye infection. Pinch injuries 	45	4	3	12	345	4	1	4	-
6.	Compression	Maintena nce and cleaning	 Sharp edges. Ungraded parts Defective tools & tackles. Electrocution. 	A	 Awkward posture Entanglement Struck by an object. Slippery tools Cut injuries 	35	3	3	9	345	3	1	3	-
7.	Compre ssion	Entry, Exit way	Slip & trip hazardLow space	A	 Fall of personal & material. Poor housekeeping 	35	2	2	4	345	2	1	2	-
8.	Compre ssion	Packing	• Static charge Defective poly bag.	A	Fire.Spillage	35	2	2	4	345	2	1	2	-

FORMAT No.: Page 3 of 5



ENVIRONMENT HEALTH SAFETY DEPARTMENT

HAZARD IDENTIFICATION AND RISK ASSESSMENT



Frequency

MATRIX

	5	5	10	15	20	25
SEVERITY	4	4	8	12	16	20
VE	3	3	6	9	12	15
SE	2	2	4	6	8	10
	1	1	2	3	4	5
	0	1	2	3	4	5

Frequency

LOW MODERATE HIGH

FORMAT No.:



ENVIRONMENT HEALTH SAFETY DEPARTMENT

HAZARD IDENTIFICATION AND RISK ASSESSMENT

REVISION HISTORY - HIRA Register Revision No.	Date	Reason for change	Originator (Leader)	Approval					
			Plant/Functional Manager	Plant/ Functional Head					
Distribution: Leader /plant/functional Head(s) /Functional Head – EHS									

	Prepared By Operating Officer/Executive	Reviewed By Operating Manager	Approved By Department Head	Authorized By Head QA
Sign				
Date				
Name				

FORMAT No.: Page 5 of 5