


PRODUCTION DEPARTMENT

Departi	nent: Production	SOP No.:		
<b>Title:</b> Cleaning and Operation of Fluidized Bed Dryer (GM 30/45 HW)		Effective Date:		
Superse	des: Nil	Review Date:		
Issue Da	ate:	Page No.:		
Vernacı	llar SOP: No			
1.0	OBJECTIVE:			
1.1	To lay down a procedure for Cleaning and Operation of Fluid Bed Dr	yer (GM 30/45 HW).		
2.0	SCOPE:			
2.1	This procedure is applicable to Cleaning and Operation of Fluid Beamanufacturing area.	l Dryer (GM 30/45 HW) located in		
3.0	<b>RESPONSIBILITY:</b>			
3.1	Technical Associate : Cleaning and Operation			
3.2	Production Officer/Executive : Checking cleaning and operation			
3.3	Head Production : SOP Compliance			
3.4	IPQA Person : Line Clearance			
4.0	<b>DEFINITION (S):</b>			
4.1	NA			
5.0	PROCEDURE:			
5.1	"TYPE A" CLEANING:			
	Change over from one batch to next batch of the same product and same potency and of similar			
	product with ascending potency.			
5.1.1	Remove "EQUIPMENT STATUS" label and affix dully filled "UNDER CLEANING" label to the machine.			
5.1.2	Enter the cleaning start time in equipment usage log sheet as per SOP (Making entries in equipmen usage and cleaning log sheet).			
5.1.3	Shake the finger bag in manual mode to dedust.			
5.1.4	Remove the remainants of the previous batch from the equipment and	the area with vacuum cleaner.		
5.1.5	Allow sucking the powder attached with the wall and return riser usin			
5.1.6	Clean the plenum, bag chamber, inlet and outlet air ducts from outsid	e using a dry clean lint free duster.		
5.1.7	Clean the product container bowl with dry lint free cloth to remove an	v laftavar matarial		



PRODUCTION DEPARTMENT

	STANDARD OPERATING PROCEDUR			
Departn	nent: Production	SOP No.:		
Title: Cleaning and Operation of Fluidized Bed Dryer (GM 30/45 HW)Effective Date:Supersedes: NilReview Date:		Effective Date:		
		<b>Review Date:</b>		
Issue Da	te:	Page No.:		
5.1.8	Affix dully filled status label on RMG as "CLEANED" with date a	and signature of Production Officer		
	verified by QA officer.			
5.1.9	Record the cleaning completion time in equipment usage log she	Record the cleaning completion time in equipment usage log sheet as per SOP (Making entries in		
	equipment usage and cleaning log sheet).			
5.2.	<b>"TYPE B" CLEANING:</b>			
	This is a cleaning procedure for Changeover of product with	different actives/color/descending		
	potency or after maintenance of contact parts.			
5.2.1	Follow the procedure from step 5.1.1 to 5.1.4.			
5.2.2	Bring down the finger bag by operating the finger bag handle towards lower side.			
5.2.3	Remove the bag from the finger holding ring and clean the bag.			
5.2.4	Pull out the product container bowl; dismantle the view glass (1 nos.) of product container bowl as			
	viewing glass (2 nos.) of bag chamber.			
5.2.5	Scrub the bag chamber, explosion chamber and finger bag holder	ring and view glasses with gasket		
	inflated gasket (2 nos.), and inflated tube ring with a nylon scrubber u	using purified water from inside and		
	outside to remove any adhered material.			
5.2.6	Cleaning shall be performed for the Inlet Duct and Outlet Duct prio	r to dampers with high pressure jet		
	cleaner and cleanliness shall be ensured up to maximum accessible ar	ea.		
5.2.7	Use the ladder to clean the outer surface of bag chamber.			
5.2.8	Rinse all the above parts with 30-40 liters of purified water.			
5.2.9	Scrub the product container bowl and trolley with a nylon scrubber us	sing purified water.		
5.2.10	Remove the gasket Dutch weave sieve and the supporting plate.			
5.2.11	Place the sieve in a horizontal position. Scrub the sieve with a ny	vlon scrubber using 10-15 liters of		
5.2.12	purified water. Scrub the supporting plate with a nylon scrubber using purified water.			
5.2.12	Rinse the product container bowl, sieve and supporting plate with 10-			
5.2.13	Place the sieve and the supporting plate on a clean S.S. pellet. Reass			
5.2.14	plate.	sentere de sieve and the supporting		
5.2.15	Scrub the outside of the FBD, supporting arms inlet air duct and the i	nlet chamber with a nylon scrubbe		
-	using 40-50 liters of purified water.			






#### STANDARD OPERATING PROCEDURE

STANDARD OF ERATING TROCEDORE		
Department: Production	SOP No.:	
Title: Cleaning and Operation of Fluidized Bed Dryer (GM 30/45 HW)Effective Date:		
Supersedes: Nil	<b>Review Date:</b>	
Issue Date:	Page No.:	

- 5.2.16 Clean the outer surface of FBD; supporting arms inlet air duct and inlet air chamber with 10-15 liters of purified water.
- 5.2.17 Clean the utility cables limit switches and control panel with a dry lint free duster.
- 5.2.18 Reassemble the view glasses of product container of bowl and bag chamber.
- 5.2.19 Put the cleaned FBD finger bag and RMG filter bag in FBD bowl.
- 5.2.20 Assemble the FBD and operate the FBD at an inlet temperature of 65°C until the out let temperature is achieved 63°C to 65°C. Ensure the bags are completely dried Remove the bags and transfer it to the granulation spare area.
- 5.2.21 Rinse the FBD bowl, bag chamber, explosion chamber and view glasses with 25-35 Liters of purified water.
- 5.2.22 Wipe out the body of FBD, bag chamber, explosion chamber, trolley and bowl with a clean dry lint free duster.
- 5.2.23 Wipe all the above parts with 70% v/v IPA solution.
- 5.2.24 Replace the "UNDER CLEANING" status label with the "CLEANED" status label with date and signature of Production Officer and QA Officer.
- 5.2.25 Record the cleaning completion time in equipment usage log sheet as per SOP (Making entries in equipment usage and cleaning log sheet).
- 5.2.26 Record the cleaning checklist.

### 5.3 Frequency:

- 5.3.1 Type 'A' cleaning is applicable after completion of every batch of same product, same potency and of similar product with ascending potency. If same product is processed for more than seven days then follow the procedure of type B cleaning.
- 5.3.2 Type 'B' cleaning is applicable in case of changeover of product with different actives/color/descending potency or after maintenance of contact parts or same product is run for more than seven days cleaning Type B done after completion of batch.
- 5.3.3 Cleaning (Dedusting of machine with vacuum cleaner and dry lint free cloth) is applicable in case of at the end of working day.





STANDARD OPERATING PROCEDURE			
Department: Production SOP No.:			
Title: Cleaning and Operation of Fluidized Bed Dryer (GM 30/45 HW)	Effective Date:		
Supersedes: Nil	Review Date:		
Issue Date:	Page No.:		

**NOTE:** After Type - B cleaning, if machine is not used within 72 hours, clean the machine "before use", with the lint free duster dipped in 70% v/v IPA solution followed by dry lint free duster and dully sign the "CLEANED" label again. Record the activity in equipment usage log sheet as per SOP (Making entries in equipment usage and cleaning log sheet).

#### 5.4 **OPERATION:**

### 5.4.1 Machine setting:

- 5.4.1.1 Ensure 'CLEANED' label duly filled and signed is affixed on the equipment.
   Ensure cleanliness of area and the equipment. Record the observations in the equipment usage log sheet.
   Affix 'UNDER PROCESS' label duly filled and signed on the equipment.
- 5.4.1.2 Open the lock of control panel. Turn main switch to 'MAINTAIN' or 'AUTO' position. Reading on main air pressure gauge will start increasing and opening screen will appear on MMI. Ensure the Compressed air pressure should be between 5 bar.
- 5.4.1.3 Touch 'MAIN MENU' on MMI. Main menu screen will appear. Touch 'LOGIN' ON MMI. Keypad will appear. Load correct password and then touch 'ENTER' for confirmation.
- 5.4.1.4 Touch 'MANUAL' on MMI. Manual mode main screen will appear.
- 5.4.1.5 Touch 'BAG LIFT LOWR' on MMI. Pneumatic cylinder will come down.
- 5.4.1.6 Fix the FBT supporting ring at the fringes of finger bag and tight the rope.
- 5.4.1.7 Fix each finger one by one on the respective hook on the finger bag hanger.
- 5.4.1.8 Clamp the finger bag hanger on the pneumatic cylinder.
- 5.4.1.9 Attach the compressed air supply pipes to FBT supporting ring.
- 5.4.1.10 Touch 'BAG LIFT LOWR' on MMI. Pneumatic cylinder will start lifting up. Manually guide the guide rollers into the track.
- 5.4.1.11 Place the FBD bowl containing material to be dried in between the lower plenum and retarding chamber and lock the clamps. Insert the product bed temperature sensor in the temperature sensor port of product container.
- 5.4.1.12 Touch 'PC SEAL VENT' on MMI. Pressure reading on the PC pressure gauge shall increase to 2.0 to 2.5 bar.
- 5.4.1.13 Touch 'FBD SEAL VENT' on MMI. Pressure reading on the FBT pressure gauge shall increase to 2.0 to 2.5 bars.



PRODUCTION DEPARTMENT

STANDARD OPERATING PROCEDURE		
Department: Production	SOP No.:	
Title: Cleaning and Operation of Fluidized Bed Dryer (GM 30/45 HW)	Effective Date:	
Supersedes: Nil	<b>Review Date:</b>	
Issue Date:	Page No.:	

5.4.1.14 Touch 'MAIN MENU' on screen. Main menu screen will appear.
 Note: Turn OFF the main compressed air while hanging the FBD finger bag or whenever the pneumatic cylinder is lifted lower.

### 5.4.2 Recipe Edit / Load / Delete:

- 5.4.2.1 Recipe can de edited / loaded / deleted in both auto and manual mode.
- 5.4.2.2 Touch 'RECIPE' on MMI. Recipe main screen will appear.
- 5.4.2.3 Touch 'EDIT' on MMI. Recipe edit main screen will open with following menu: 'Program No., Product Name, Batch No., Lot No., Operator Code, FBD Tag No., Product Code, Batch size, Manufacturing Date, Expiry Date'.
- 5.4.2.4 Load Product Name, Batch No., Lot No., FBD Tag No., Product Code, Batch size, Manufacturing Date, Expiry Date as per respective BMR.
- 5.4.2.5 Touch 'NEXT' on MMI. 'RECIPE EDIT-1' screen will open with following menu:
  'Process Time, Air Dry Time, Spray Time, Spray OFF Time, Spray ON Time, Shaking
  Interval, Shaking Duration, Piston Up, Piston Down, Cooling Time, End Shaking Time, Piston Up,
  Piston Down'.
- 5.4.2.6 Load Process Time, Air Dry Time, as per respective BMR.
- 5.4.2.7 Touch 'NEXT' on MMI. 'RECIPE EDIT-1' screen will open with following menu: 'Inlet Temperature, Outlet Temperature, Inlet High, Spray Temperature, RH Set Point, print Interval, DP across HEPA Set, DP across FBT set, Spray Pump speed'.
- 5.4.2.8 Load inlet temperature, outlet temperature, inlet high temperature, RH set point, print Interval, DP across HEPA, and DP across finger bag.
- 5.4.2.9 Touch 'LOAD' on MMI. Recipe load screen will open and it displays the loaded process parameter's details.
- 5.4.2.10 Touch 'STORE' on MMI. Keypad will open. Give suitable name or code for the recipe. Recipe will be get loaded in the PLC memory under given name or code.
- 5.4.2.11 Touch 'MAIN SCREEN' on MMI. Recipe main screen will open.
- 5.4.2.12 To load already exist recipe Touch 'LOAD' on MMI. Stored recipe list will open. Select the recipe and touch 'ESC' on MMI. Warning 'LOAD RECIPE XYZ' (XYZ indicates name or code for a particular recipe). Touch 'YES' to load the selected recipe.



PRODUCTION DEPARTMENT

#### STANDARD OPERATING PROCEDURE

Department: Production	SOP No.:	
Title: Cleaning and Operation of Fluidized Bed Dryer (GM 30/45 HW)	Effective Date:	
Supersedes: Nil	<b>Review Date:</b>	
Issue Date:	Page No.:	

5.4.2.13 To delete already exist recipe touch 'DELETE' on MMI. Stored recipe list will open. Select the recipe and touch 'ESC' on MMI. Warning 'DELETE RECIPE XYZ' (XYZ indicates name or code for a particular recipe). Touch 'YES' to delete the selected recipe.

#### 5.5 Manual Mode Operation:

- 5.5.1 Ensure main switch of control panel is at 'MAINTAIN' position.
- 5.5.2 Touch 'LOGIN' and enter the password.
- 5.5.3 After completion of machine setting touch 'MANUAL' on screen. Manual mode main screen will open.
- 5.5.4 Touch 'MAN-1' on MMI. Man-1 screen will open.
- 5.5.5 Touch 'BLOWER' on MMI. Blower will start. Touch Inlet Damper and Hot Water to start.
- 5.5.6 Touch 'BYPASS DAMPER' on MMI. Bypass Damper screen will open. Current status

of the inlet air temperature, outlet air temperature, product bed temperature, air velocity and DP across HEPA and finger bag will also displayed on this screen. Set the bypass damper ON/OFF % depending on the inlet air, outlet air and product bed temperature. Touch 'BYPASS DAMPER' ON MMI to ON / OFF the by pass damper.

- 5.5.7 Touch 'PRV' to open previous screen.
- 5.5.8 At the end of operation touch 'BLOWER' on MMI. Blower will stop.
- 5.5.9 Touch 'MAN' on MMI. Manual mode main screen will open.
- 5.5.10 In case of "AUTO" mode failure during batch processing, machine can be run in "MANUAL" mode to Complete the batch by intimating to QA and Engineering department.

### 5.6 Auto Mode Operation

- 5.6.1 Ensure main switch of control panel is at 'AUTO' position.
- 5.6.2 Touch 'LOGIN' and enter the password.
- 5.6.3 Touch 'AUTO' on MMI. Auto selected screen will open and it displays inlet, outlet and product bed temperature.
- 5.6.4 Touch 'START' to start the process on MMI.
- 5.6.5 Touch 'HOT WATER' on MMI. Hot water setting screen will open. Set Hot water ON and OFF time.
- 5.6.6 Touch 'PREV' on MMI. Auto selected screen will open.

PRODUCTION DEPARTMENT

	NH .
÷ 2	

STANDARD OPERATING PROCEDURE		
Department: Production	SOP No.:	
Title: Cleaning and Operation of Fluidized Bed Dryer (GM 30/45 HW)	Effective Date:	
Supersedes: Nil	<b>Review Date:</b>	
Issue Date:	Page No.:	

- 5.6.7 Touch 'IND' on MMI. Next screen will open and it displays current process status for example 'Air Dry Time Started'. Set and actual values for Inlet, outlet and product bed temperature, DP across HEPA and finger bag and air velocity will also displayed on screen.
- 5.6.8 Touch 'IND 2' on MMI. Screen will show set and actual RH and % of FC damper opening, set and actual % opening of the by pass damper.
- 5.6.9 Touch 'MAN' on MMI. Auto selected main screen will open.
- 5.6.10 Process will run as per set parameters and stops automatically on completion of cycle.
- 5.6.11 Touch 'MAIN SCREEN' on MMI. Main screen will open. Touch 'LOGOUT' on MMI. 'OK, you are Logged Out' message will display on MMI.

## 5.7 Product Unloading:

- 5.7.1 Open Manual mode main screen.
- 5.7.2 Touch 'PC SEAL VENT' on MMI. Pressure reading on the PC pressure gauge shall decrease to 0 bar.
- 5.7.3 Touch 'FBD SEAL VENT' on MMI. Pressure reading on the FBT pressure gauge shall decrease to 0 bar.
- 5.7.4 Touch 'MAIN MENU' on screen. Main menu screen will appear.
- 5.7.5 Touch 'OPENING SCREEN' on MMI. Opening screen will open.
- 5.7.6 Remove out the product bed temperature sensor.
- 5.7.7 Open the Clamps and remove out the product container.
- 5.7.8 Touch 'BAG LIFT LOWR' on MMI. Pneumatic cylinder will come down.
- 5.7.9 Remove individual finger of finger bag from the hooks of finger bag hanger.
- 5.7.10 Remove the compressed air supply pipes from FBT supporting ring.
- 5.7.11 Uptight the rope around FBT supporting ring and take out the finger bag.
- 5.7.12 Turn main switch to 'OFF' position. MMI will turn OFF and reading on main air pressure will reduce to 0 bar and lock the control panel.
- 5.7.13 Affix 'TO BE CLEANED' label duly filled and signed on the FBD and record the observations in equipment usage log sheet as per SOP (Making entries in equipment usage and cleaning log sheet).

## 5.8 SFM (Solid Flow Monitor) Challenge Test:

5.8.1 Replace the 'CLEANED' label and affix 'EQUIPMENT STATUS' label dully filled and signed on the equipment (In Case of cleaned equipment). Or it can performed during "Type-B" cleaning.



PRODUCTION DEPARTMENT

STANDARD OPERATING PROCEDURE		
Department: Production	SOP No.:	
Title: Cleaning and Operation of Fluidized Bed Dryer (GM 30/45 HW)	Effective Date:	
Supersedes: Nil	<b>Review Date:</b>	
Issue Date:	Page No.:	

- 5.8.2 Take 200 grams of starch and put it in the FBD bowl.
- 5.8.3 Start the FBD in Auto Mode with 20% exhaust flap open.
- 5.8.4 The FBD should be tripped as the starch comes in contact with SFM.
- 5.8.5 After reset of SFM the machine can be started.
- 5.8.6 Record the activity in equipment usage log sheet as per SOP (Making entries in equipment usage and cleaning log sheet) and in SFM Challenge test annexure-I (SFM (Solid Flow Monitor) Challenge Test).
- 5.8.7 Again take 200 grams of starch and put it in the FBD bowl.
- 5.8.8 Start the FBD in Manual Mode with 20% exhaust flap open.
- 5.8.9 The FBD should be tripped as the starch comes in contact with SFM.
- 5.8.10 After reset of SFM the machine can be start.
- 5.8.11 Record the activity in equipment usage log sheet as per SOP (Making entries in equipment usage and cleaning log sheet) and in SFM Challenge test annexure-I (SFM (Solid Flow Monitor) Challenge Test).
- 5.8.12 After "SFM Challenge Test", Type B cleaning should be performed. And the same should be recorded in equipment usage log sheet as per SOP (Making entries in equipment usage and cleaning log sheet).
- 5.8.13 If 'SFM Challenge Test' not complies then inform to Production head and Maintenance head and after rectification again perform the 'SFM Challenge Test' and record the same in equipment usage log book.
- 5.8.14 SFM sensor cleaning is to be performed at the end of week by maintenance personnel with internal communication from production to maintenance department and record the details in Annexure III (SFM sensor weekly cleaning record).
- 5.8.15 **Frequency:** First week of the Month.

PRODUCTION DEPARTMENT



STANDARD OPERATING PROCEDURE				
Department: Production SOP No.:				
Title: Cleaning and Operation of Fluidized Bed Dryer (GM 30/45 HW)	Effective Date:			
Supersedes: Nil	Review Date:			
Issue Date:	Page No.:			

## 6.0 ABBREVIATION (S):

6.1	FBD	: Fluidized Bed Drier
6.2	IPA	: Iso Propyl Alcohol
6.3	QA	: Quality Assurance
6.4	SS	: Stainless Steel.
6.5	SOP	: Standard Operating Procedure
6.6	v/v	: Volume/Volume
6.6	BMR	: Batch Manufacturing Record
6.7	MMI	: Man Machine Interface
6.8	HEPA	: High efficiency particulate air
6.9	PC	: Product Container
6.10	DP	: Differential Pressure
6.11	FBT	: Finger Bag Tube
6.12	FC	: Flow Control
7.0	REFE	RENCES (S):
7.1	SOP: N	Making entries in equipment usage and cleaning log sheet.
7.2	SOP: O	Cleaning of production area.
7.3	SOP: S	Status Labeling
7.4	SOP: O	Cleaning and utilization of FBD finger bag and RMG filter bag.

### 8.0 ANNEXURE (S):

Annexure no.	Title of Annexure	Format No.	Mode of Execution
Annexure-I	SFM (Solid Flow Monitor) Challenge Test		Logbook
Annexure-II	Cleaning checklist of FBD (GM 30/45		Logbook
	HW)		
Annexure-III	SFM sensor weekly cleaning record		Logbook

### 9.0 **DISTRIBUTION:**

9.1 Master Copy : Quality Assurance



PRODUCTION DEPARTMENT

STANDARD OPERATING PROCEDU	RE
Department: Production	SOP No.:
Title: Cleaning and Operation of Fluidized Bed Dryer (GM 30/45 HW)	Effective Date:
Supersedes: Nil	Review Date:
Issue Date:	Page No.:

9.2 **Controlled Copy (s):** Production Department (1), Quality Assurance (1)

9.3 **Reference Copy (s):** Production Department (1)

### **10.0 REVISION HISTORY:**

S.No.	Version No.	Change Control No.	Reason (s) For Revision	Details of Revision	Effective Date
1.	00	NA	New SOP	NA	NA

					RODUCTION DEPART					
				STANDARD O	PERATING I	PROCEDURE				
Departm	ent: Production						SOF	No.:		
Title: Cle	aning and Operation of Flu	idized Bed	Dryer (GM	A 30/45 HW)			Effe	ctive Date:		
Supersed	es: Nil						Rev	ew Date:		
Issue Dat	æ:						Page	e No.:		
			S	A) FM (Solid Flov	NNEXURE I w Monitor) Cl	nallenge Test				
	FBD ID No.:		-					YEAR	:	
DATE	Quantity of Starch Used	ACTI	VITY	CHALLEN AUTO		CHALLEN MANUA	NGE TEST L MODE	DONE BY	CHECKED BY	REMARKS
		FROM	ТО	COMPLIES	NOT COMPLIES	COMPLIES	NOT COMPLIES			



PRODUCTION DEPARTMENT

STANDARD OPERATING PROCEDURE				
Department: Production	SOP No.:			
Title: Cleaning and Operation of Fluidized Bed Dryer (GM 30/45 HW)	Effective Date:			
Supersedes: Nil	Review Date:			
Issue Date:	Page No.:			

## ANNEXURE II CLEANING CHECKLIST OF FBD (GM30/45 HW)

Name of the Equipment		Fluidized Bed dryer (GM30/45 HW)	
Equipment I.D. No.		Previous product	
Batch No.		Date	

S.No.	Activity	Activity performed
1.	Shake the finger bag in manually mode to dedust.	
2.	Remove the remainants of the previous batch from the equipment and the area with vacuum cleaner.	
3.	Allow sucking the powder attached with the wall and return raiser using vacuum cleaner.	
4.	Bring down the finger bag by operating the finger bag handle towards lower side.	
5.	Remove the bag from the finger holding ring and clean the bag.	
6.	Pull out the product container bowl; dismantle the view glass (1 nos.) of product container bowl and viewing glass (2 nos.) of bag chamber.	
7.	Scrub the bag chamber, explosion chamber and finger bag holder ring and view glasses with gasket, inflated gasket (2 nos.), and inflated tube ring with a nylon scrubber using purified water from inside and outside to remove any adhered material.	
8.	Clean the Inlet Duct and Outlet Duct prior to dampers with high pressure jet cleaner and cleanliness shall be ensured up to maximum accessible area.	
9.	Use the ladder to clean the outer surface bag chamber.	
10.	Rinse all the above parts with 30-40 liters of purified water.	
11.	Scrub the product container bowl and trolley with a nylon scrubber using purified water.	
12.	Remove the gasket Dutch weave sieve and the supporting plate.	
13.	Place the sieve in a horizontal position. Scrub the sieve with a nylon scrubber using 10-15 liters of purified water.	
14.	Scrub the supporting plate with a nylon scrubber using purified water.	
15.	Rinse the product container bowl, sieve and supporting plate with 10-15 liters of Purified water.	
16.	Place the sieve and the supporting plate on a clean S.S. pellet.	
17.	Reassemble the sieve and the supporting plate.	
18.	Scrub the out side of the FBD, supporting arms inlet air duct and the inlet chamber with a nylon scrubber using 40-50 liters of purified water.	



PRODUCTION DEPARTMENT

### STANDARD OPERATING PROCEDURE

Department: Production	SOP No.:
Title: Cleaning and Operation of Fluidized Bed Dryer (GM 30/45 HW)	Effective Date:
Supersedes: Nil	<b>Review Date:</b>
Issue Date:	Page No.:

S.No.	Activity	Activity performed
19.		
	chamber with 10-15 liters of purified water.	
20.	Clean the utility cables limit switches and control panel with a dry lint free	
	duster.	
21.	Reassemble the view glasses of product container of bowl and bag chamber.	
22.	Put the cleaned FBD finger bag and RMG filter bag in FBD bowl.	
23.	Assemble the FBD and operate the FBD at an inlet temperature of 65°C until the out let temperature is achieved 63°C to 65°C. Ensure the bags are completely dried Remove the bags and transfer it to the granulation spare area.	
24.	Rinse the FBD bowl, bag chamber, explosion chamber and view glasses with 25- 35 liters of purified water.	
25.	Wipe out the body of FBD, bag chamber, explosion chamber, trolley and bowl with a clean dry lint free duster.	
26.	Wipe all the above parts with 70% w/w IPA solution.	

Checked By (Prod.) Sign/Date Verified By (QA) Sign/Date

Note: Put ' $\sqrt{}$ ' mark if activity is performed and put 'X' if activity is not performed.

PRODUCTION DEPARTMENT

STANDARD OPERATING PROCEDURE					
Department: Production	SOP No.:				
Title: Cleaning and Operation of Fluidized Bed Dryer (GM 30/45 HW)	Effective Date:				
Supersedes: Nil	Review Date:				
Issue Date:	Page No.:				

### ANNEXURE III SFM SENSOR WEEKLY CLEANING RECORD

DATE	CLEA	NING	DONE BY	Y CHECKED BY	E BY CHECKED BY REMAN	REMARKS
	FROM	ТО				